

PIT STATUS EVALUATION FORM

Facility ID: 115058

Pit Name: STATE 1-36 & 2-36

☐ Duplicate Record(s) Pit #



Legend

- Database Pit Location
- Producing Well
- Shut In Well
- ✦ Temp Aban Well
- ✦ Abandoned Well
- ✦ Dry & Aban Well
- ◆ Injection Well
- Other Well Status



1:6,000
0 250 500 750 Feet

Image Source:
USDA National Agricultural Imagery
Program (NAIP), 2006

 S.S. PAPADOPOULOS & ASSOCIATES, INC.

COGCC Database Information

Status: NR Owner: MARLIN OIL CO* THE
T: 8S R: 57W Sec: 36 QQ: NWSE 6th Meridian
Latitude: 39.307603 Longitude: -103.72213 NAD83

County: Elbert, CO
County Code: 039

Pit Status Evaluation

☐ Active

- ☐ Form 15: Pit Permit (1986) existing Assoc. Well Seq No(s) _____
☐ Other documentation _____
☐ Aerial photo verification _____

☒ Closed

- ☐ Form 27: Remediation Workplan _____
☐ Form 4: Sundry Notice (1986) oil spill from broken valve
☐ Rule 903a.(2)B
☒ Evidence pit(s) existed, no closure docs & well not PR, AC or SI
Well API Seq #(s) 06551, 06564, 06557 (1998)
☒ Other documentation #651628 and # 479722 (1996)

☐ Abandoned

☐ Possible un-reclaimed pit(s) or adverse conditions, no closure docs

- ☐ Site Visit
☐ No Site Visit
☐ Add'l Review

☐ Unknown

Notes: Multi-well use: State 2-36 #05-039-06551 or 05-039-06564 PA (6-10-1998)
State 1-36 #05-039-06557 PA (5-29-98) and FIR (8-28-96) indicates
no pit -> disposal wells for produced water