

Final Reclamation and Stormwater Inspection

March 1, 2019

Operator: NOBLE ENERGY INC # 100322

Location ID: 327252

Inspection Document #: 674902638

Weld County, CO

NENE Section 21 T2N R64W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: NOBLE ENERGY INC /2N64W21
Location ID: 327252



Photo 1. Photo taken from the access road off CR 55, facing West. Photo depicts current access road condition.



Photo 2. Photo taken from the access road off CR 55, facing East. Photo depicts current access road condition.

Inspection Photos
Location Name: NOBLE ENERGY INC /2N64W21
Location ID: 327252



Photo 3. Photo taken from the access road, facing West. Photo depicts recent pipeline removal work on the north side of the road.



Photo 4. Photo taken from the location, facing North. Photo depicts recent pipeline removal work and a new line marker installed according to the complainant.

Inspection Photos
Location Name: NOBLE ENERGY INC /2N64W21
Location ID: 327252



Photo 5. Photo taken from the location, facing East. Photo depicts recent pipeline and tank battery removal work according to the complainant.



Photo 6. Photo taken from the location, facing North. Appears the operator has not performed reclamation activities with gravel remaining on location.

Inspection Photos
Location Name: NOBLE ENERGY INC /2N64W21
Location ID: 327252



Photo 7. Photo taken from the location. See comments from Photo 6.



Photo 8. Photo taken from the location, facing South. Photo depicts the recent pipeline removal work in the background and the remaining access road and gravel in the foreground.

Inspection Photos
Location Name: NOBLE ENERGY INC /2N64W21
Location ID: 327252



Photo 9. Photo taken from the location, facing East. Photo depicts recent pipeline and tank battery removal work according to the complainant.



Photo 10. Photo taken from the western perimeter of the location. Photo depicts the culvert that was damaged/crushed during the pipeline removal work.

Inspection Photos
Location Name: NOBLE ENERGY INC /2N64W21
Location ID: 327252



Photo 11. Photo taken from the location, facing East.
Photo depicts current access road condition.



Photo 10. Photo taken from the access road, facing West.
Photo depicts current access road condition.