

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/27/2019

Submitted Date:

02/28/2019

Document Number:

679703139**FIELD INSPECTION FORM**

Loc ID 315215 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10654Name of Operator: LASSO OIL & GAS LLCAddress: 3021 RIDGE RD #156City: ROCKWALL State: TX Zip: 75032**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Freeman, Kris	254-717-0435	kfreeman@31operating.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
107193	PIT		09/23/1999		-	CONTINENTAL 4-8	
230427	WELL	PR	11/08/2000	GW	103-08090	CONTINENTAL 4-8	PR

General Comment:

routine well inspection

LocationOverall Good: ☐

Signs/Marker:			
Type	BATTERY		
Comment:	Sign not posted or information inaccurate at well(s) or battery. Missing nearest public road.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	04/30/2019
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 800-209-9762

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	Weeds in both pits, on location, and lease road.		
Corrective Action:	Comply with Rule 603.f .	Date:	04/03/2019
Type	UNUSED EQUIPMENT		
Comment:	Unused pipe on location.		
Corrective Action:	Comply with Rule 603.f .	Date:	05/30/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	
In Containment: No			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	PIT		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		

Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	107193	Type:	PIT	API Number:	-	Status:		Insp. Status:	
Facility ID:	230427	Type:	WELL	API Number:	103-08090	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing well								
Corrective Action:							Date:		

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction		Compaction				

Comment: _____

Corrective Action: _____

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PITType: BlowdownLined: NOPit ID: 107193Lat: 39.799510Long: -108.643160

Reference Point: _____

Other: _____

Length: _____

Width: _____

Lining:

Liner Type: _____

Liner Condition: _____

Comment: _____

Corrective Action

Date: _____

Fencing:Fencing Type: WildlifeFencing Condition: Adequate

Comment: _____

Corrective Action

Date: _____

Netting:

Netting Type: _____

Netting Condition: _____

Comment: _____

Corrective Action

Date: _____

Anchor Trench Present: _____

Oil Accumulation: _____

2+ feet Freeboard: YES

Comment: _____

Corrective Action

Date: _____

Type: BlowdownLined: NOPit ID: 107193Lat: 39.799740Long: -108.643150

Reference Point: _____

Other: _____

Length: _____

Width: _____

Lining:

Liner Type: _____

Liner Condition: _____

Comment: _____

Corrective Action

Date: _____

Fencing:Fencing Type: WildlifeFencing Condition: Adequate

Comment: _____

Corrective Action

Date: _____

Netting:

Netting Type: _____

Netting Condition: _____

Inspector Name: Moran, Rick

Comment:		Date:
Corrective Action		
Anchor Trench Present:	Oil Accumulation:	2+ feet Freeboard: <u>YES</u>
Comment:		Date:
Corrective Action		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401956112	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4749615
679703140	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4749597