

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/27/2019

Submitted Date:

02/28/2019

Document Number:

688800471**FIELD INSPECTION FORM**

Loc ID 325409 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 14 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|--------------|--------------------------|---------------------------------------|
| Inspections, All | | SanJuanCOGCC@bp.com | SW Inspection Reports |
| Beebe, Sabre | 970-779-9398 | Sabre.Beebe@bpx.com | SW Inspection Reports |
| Fischer, Alex | | alex.fischer@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 214726 | WELL | PR | 09/01/2018 | GW | 067-06330 | SHARP 1E | EI |

General Comment:

On February 27, 2019 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Sharp #1E. For the most recent field inspection report of this facility, please refer to document #685302907.

| Location | | | |
|--|--|--------|-----------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Access road was snow covered at the time of this inspection. | | |
| Corrective Action: | | Date: | |
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Free standing sign near PBV. | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Free standing sign near location entance. Sign is illegible. | | |
| Corrective Action: | Install sign to comply with Rule 201.b. | Date: | 03/28/2019 |
| Emergency Contact Number: | | | |
| Comment: | Posted on location signs. | | Date: _____ |
| Corrective Action: | | | |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | SEPARATOR | | |
| Comment: | Stock panel enclosure around separator and PBV. | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Stock panel enclosure. | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | Stock panels around telemetry equipment. | | |
| Corrective Action: | | Date: | |
| Equipment: | | | |
| Type: Gas Meter Run | # 1 | | corrective date |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Telemetry equipment. | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|-----|--|-------|
| Type: Bird Protectors | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Deadman # & Marked | # 4 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Flow Line | # 2 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|-----------|-----------|---------|-----------------------|
| PRODUCED WATER | 1 | <100 BBLS | PBV STEEL | | 37.079162,-107.889011 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | 95 bbl. | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|--|---------------------|---------------------|-------------|
| | | | | |
| Comment: | Location was snow covered during this inspection, berms were not observed. | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|--|-------|
| Yes/No | | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 214726 Type: WELL API Number: 067-06330 Status: PR Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |
| Compaction | Pass | Compaction | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

| Comment | User | Date |
|---|----------|------------|
| On February 27, 2019 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Sharp #1E. For the most recent field inspection report of this facility, please refer to document #685302907. During this inspection, it was observed that the location sign is illegible. | hughesjo | 02/28/2019 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 401955813 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4749024 |
| 688800472 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4749015 |