

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/28/2019

Submitted Date:

02/28/2019

Document Number:

689303396**FIELD INSPECTION FORM**

Loc ID 424796	Inspector Name: Holtz, Darin	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> OGCC Operator Number: <u>10531</u> Name of Operator: <u>VANGUARD OPERATING LLC</u> Address: <u>5847 SAN FELIPE #3000</u> City: <u>HOUSTON</u> State: <u>TX</u> Zip: <u>77057</u>				<b>Findings:</b> <u>27</u> Number of Comments <u>2</u> Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested <b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

**Contact Information:**

Contact Name	Phone	Email	Comment
Collett, Shane		scollett@vnrenergy.com	Superintendent operations
Ghan, Scott	970-744-8128	sghan@vnrenergy.com	SR. EH&S
Aaron, Axelson	230-0926	aaxelson@vnrenergy.com	Sr. Production Foreman

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
424800	WELL	PR	06/13/2012	GW	045-20942	EPPERLY 23A-23-692	PR
424802	WELL	PR	07/19/2012	GW	045-20943	EPPERLY 13D-23-692	PR
424803	WELL	PR	07/26/2012	GW	045-20944	EPPERLY 14B-23-692	PR
424807	WELL	PR	07/19/2012	GW	045-20945	EPPERLY 13C-23-692	PR
424808	WELL	PR	07/26/2012	GW	045-20946	EPPERLY 24D-23-692	PR
424809	WELL	PR	07/19/2012	GW	045-20947	EPPERLY 13A-23-692	AC
424810	WELL	PR	06/13/2012	GW	045-20948	EPPERLY 23B-23-692	PR
424811	WELL	PR	07/23/2012	GW	045-20949	EPPERLY 23D-23-692	PR
424813	WELL	PR	06/13/2012	GW	045-20950	EPPERLY 23C-23-692	PR
424815	WELL	PR	07/10/2012	GW	045-20951	EPPERLY 13B-23-692	PR
424816	WELL	PR	07/26/2012	GW	045-20952	EPPERLY 24B-23-692	AC
424932	WELL	PR	07/26/2012	GW	045-20979	Epperly 14D-23-692	PR

**General Comment:**

Routine Field Inspection.  
Location is snow covered.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Snow packed /icy.			
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Emergency Contact Number:				
Comment:	1-800-921-8252			
Corrective Action:				Date: _____
<b>Good Housekeeping:</b>				
Type	OTHER			
Comment:	Stained material under scrubber pot. see photos.			
Corrective Action:	Properly treat or dispose of oily waste in accordance with Rule 907.e.			Date: 03/04/2019
Overall Good: <input checked="" type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	SEPARATOR			
Comment:	Hog panel fence.			
Corrective Action:				Date:
Type	IGNITOR/COMBUSTOR			
Comment:	Panel gates.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Panel gates.			
Corrective Action:				Date:
<b>Equipment:</b>				
Type: Pig Station	# 1			corrective date
Comment:				
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 12			
Comment:	Leaking fittings on unit 23D, see photos.			
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.			Date: 03/04/2019
Type: Emission Control Device	# 1			
Comment:				

Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 12		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Chemical units at wellheads.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	6	500 BBLs	HEATED STEEL AST		,
Comment:	2 tanks are not heated.				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	YES		
Comment:	Bradenhead valves open top vent per sundry notice.		
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	424800	Type:	WELL	API Number:	045-20942	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	424802	Type:	WELL	API Number:	045-20943	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	424803	Type:	WELL	API Number:	045-20944	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	424807	Type:	WELL	API Number:	045-20945	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	424808	Type:	WELL	API Number:	045-20946	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	424809	Type:	WELL	API Number:	045-20947	Status:	PR	Insp. Status:	AC
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	424810	Type:	WELL	API Number:	045-20948	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	424811	Type:	WELL	API Number:	045-20949	Status:	PR	Insp. Status:	PR

<b><u>Producing Well</u></b>			
Comment:	Well Producing on plunger lift.		
Corrective Action:		Date:	
Facility ID:	424813	Type:	WELL
API Number:	045-20950	Status:	PR
Insp. Status:	PR		
<b><u>Producing Well</u></b>			
Comment:	Well Producing on plunger lift.		
Corrective Action:		Date:	
Facility ID:	424815	Type:	WELL
API Number:	045-20951	Status:	PR
Insp. Status:	PR		
<b><u>Producing Well</u></b>			
Comment:	Well Producing on plunger lift.		
Corrective Action:		Date:	
Facility ID:	424816	Type:	WELL
API Number:	045-20952	Status:	PR
Insp. Status:	AC		
<b><u>Producing Well</u></b>			
Comment:	Well Producing on plunger lift.		
Corrective Action:		Date:	
Facility ID:	424932	Type:	WELL
API Number:	045-20979	Status:	PR
Insp. Status:	PR		
<b><u>Producing Well</u></b>			
Comment:	Well Producing on plunger lift.		
Corrective Action:		Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Location is snow covered.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401956123	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4749625">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4749625</a>
689303397	Inspection photo 689303397	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4749611">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4749611</a>