

Inspection Photos

Facility ID: 257675

Operator: PIONEER NATURAL RESOURCES

Inspection Date: 3/1/2019

Inspection Photos



Photo 1. Facing south toward the recontoured and reclaimed location. Pit has been backfilled and closed.

Inspection Photos



Photo 2. Rock rip/rap is placed in the drainage channel.

Inspection Photos



Photo 3. Facing south toward the recontoured and reclaimed location. Pit has been backfilled and closed.