

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/07/2019

Submitted Date:

03/07/2019

Document Number:

687903869**FIELD INSPECTION FORM**Loc ID 333956 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Shorty, Priscilla		pshorty@hilcorp.com	
Ray, Mandi	505-324-5122	mray@hilcorp.com	
Roland, Kandis		kroland@hilcorp.com	
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258698	WELL	PR	02/22/2007	GW	067-08373	ALLISON UNIT COM 63	PR
258699	WELL	PR	02/22/2007	GW	067-08374	ALLISON UNIT COM 138	PR

**General Comment:**[Downloadable photos at the end of this inspection report.](#)

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Gravel access off county road.		
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Well location sign posted on fence at produced water tank.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Emergency contact information not posted on either the Allison Com #63 or the Allison Com #138 location signs.		
Corrective Action:	Please comply with Rule 210		Date: 04/08/2019
<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Old insulation blankets on compressor building floor.		
Corrective Action:	Please comply with Rule 603.f.		Date: 04/08/2019
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
Lube Oil			
Comment:	Localized spotting and stained gravel around compressor.		
Corrective Action:	Please comply with Rule 907.e.		Date: 04/08/2019
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	T-post and hog wire fencing around produced water tanks.		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Gas Meter Run	# 2		corrective date
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 8		
Comment:			

Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Wellheads		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	500 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	<50 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

--

**Inspected Facilities**

Facility ID: 258698	Type: WELL	API Number: 067-08373	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Facility ID: 258699	Type: WELL	API Number: 067-08374	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**Comment: [Producing.](#)

Corrective Action:

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687903870	No Emergency Contact	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4755717">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4755717</a>
687903871	No Emergency Contact	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4755719">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4755719</a>
687903872	Unused Equipment	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4755720">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4755720</a>
687903873	Localized Stained Soil	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4755721">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4755721</a>