

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

03/01/2019

Submitted Date:

03/01/2019

Document Number:

689303400

FIELD INSPECTION FORM
 Loc ID 335441 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10531

Name of Operator: VANGUARD OPERATING LLC

Address: 5847 SAN FELIPE #3000

City: HOUSTON State: TX Zip: 77057

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

19 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Aaron, Axelson	230-0926	aaxelson@vnrenergy.com	Sr. Production Foreman
Collett, Shane		scollett@vnrenergy.com	Superintendent operations
Ghan, Scott	970-744-8128	sghan@vnrenergy.com	SR. EH&S
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275527	WELL	PR	10/28/2005	GW	045-10340	WILSON 43C-23-692	PR
276317	WELL	PR	07/16/2009	GW	045-10440	WILSON 33D-23-692	PR
276318	WELL	PR	10/03/2005	GW	045-10441	WILSON 43A-23-692	PR
276319	WELL	PR	10/03/2005	GW	045-10442	WILSON 33B-23-692	PR

General Comment:
 Routine Field Inspection.
 Location is snow covered.

Location

Lease Road:			
Type	Access		
comment:	snowpacked/icy.		
Corrective ActionL		Date:	

Overall Good: ☒

Emergency Contact Number:

Comment:	1-800-921-8252	Date:	
Corrective Action:			

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	6 unmarked/unused flow line riser, see photos.		
Corrective Action:	Comply with rule 603.f. For unused , unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser	Date:	03/29/2019

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Panel gates.		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Hog panel fence.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Panel gates.		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Panel gates.		
Corrective Action:		Date:	

Equipment:

Type: Emission Control Device	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLS	STEEL AST		,
Comment:	Methanol tank near the seprators.				
Corrective Action:				Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:			Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	200 BBLS	HEATED STEEL AST		,
Comment:	1 tank is not heated.				
Corrective Action:			Date:		

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:			Date:	

Venting:

Yes/No	YES		
Comment:	Bradenhead valves open top vent per sundry notice.		

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	275527	Type:	WELL	API Number:	045-10340	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	276317	Type:	WELL	API Number:	045-10440	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	276318	Type:	WELL	API Number:	045-10441	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	276319	Type:	WELL	API Number:	045-10442	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Location is snow covered.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401956694	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4750119
689303401	Inspection photo 689303401	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4750094