

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/01/2019

Submitted Date:

03/01/2019

Document Number:

689303402

**FIELD INSPECTION FORM**

Loc ID 335442 Inspector Name: Holtz, Darin On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10531  
Name of Operator: VANGUARD OPERATING LLC  
Address: 5847 SAN FELIPE #3000  
City: HOUSTON State: TX Zip: 77057

**Findings:**

- 23 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Aaron, Axelson	230-0926	aaxelson@vnreenergy.com	Sr. Production Foreman
Ghan, Scott	970-744-8128	sghan@vnreenergy.com	SR. EH&S
Collett, Shane		scollett@vnreenergy.com	Superintendent operations

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282722	WELL	PR	10/14/2009	GW	045-11801	BBC 42C-23-692	PR
282723	WELL	PR	10/13/2009	GW	045-11800	BBC 42A-23-692	AC
282724	WELL	PR	09/24/2009	GW	045-11799	BBC 12B-24-692	AC
282726	WELL	PR	09/22/2009	GW	045-11798	BBC 13D-24-692	PR
282728	WELL	PR	09/22/2009	GW	045-11797	BBC 12D-24-692	PR
299502	WELL	PR	09/24/2009	GW	045-17688	BBC 12C-24-692	PR
299503	WELL	PR	04/17/2012	GW	045-17689	BBC 42B-23-692	AC
299504	WELL	PR	09/30/2009	GW	045-17690	BBC 12A-24-692	AC
299505	WELL	PR	10/02/2009	GW	045-17691	BBC 42D-23-692	PR

**General Comment:**

Routine Field Inspection.  
Location is snow covered.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Snow packed/ icy.		
Corrective ActionL		Date:	

Overall Good:

Emergency Contact Number:	
Comment:	1-800-921-8252
Corrective Action:	
Date:	_____

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Stained ground underneath scrubber pot on the side of the separator. see photo.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with Rule 907.e.		Date: 03/05/2019

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	Hog panel fence.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panel gates.		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Panel gates.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 9		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Chemical units at welheads.		
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 9		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 4		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	8	500 BBLs	HEATED STEEL AST		,
Comment:	4 tanks are not heated.				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	YES	
Comment:	Bradenhead valves open top vent per sundry notice.	
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	282722	Type:	WELL	API Number:	045-11801	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	282723	Type:	WELL	API Number:	045-11800	Status:	PR	Insp. Status:	AC
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	282724	Type:	WELL	API Number:	045-11799	Status:	PR	Insp. Status:	AC
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	282726	Type:	WELL	API Number:	045-11798	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	282728	Type:	WELL	API Number:	045-11797	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	299502	Type:	WELL	API Number:	045-17688	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	299503	Type:	WELL	API Number:	045-17689	Status:	PR	Insp. Status:	AC
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	299504	Type:	WELL	API Number:	045-17690	Status:	PR	Insp. Status:	AC
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				

**Producing Well**

Comment: Well Producing on plunger lift.

Corrective Action:

Date:

Facility ID: 299505 Type: WELL API Number: 045-17691 Status: PR Insp. Status: PR

**Producing Well**

Comment: Well Producing on plunger lift.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Location is snow covered.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401956696	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4750121">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4750121</a>
689303403	Inspection photo 689303403	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4750095">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4750095</a>