

Inspection Photos
Location Name: CD #3
API: 05-083-06726



CD #3 location photo.



Location drain in SW corner of location.

Inspection Photos
Location Name: CD #3
API: 05-083-06726



Mud pump gasket repair referenced in Initial Spill Report.



Mud pump room (left side of photo) where release occurred.

Inspection Photos
Location Name: CD #3
API: 05-083-06726



Terminus of drilling fluid release in perimeter ditch along N edge of location.



Lined secondary containment berm for fresh water/brine ASTs.

Inspection Photos
Location Name: CD #3
API: 05-083-06726



Northern edge of location, view to the east.



Diesel fuel container with secondary containment.

Inspection Photos
Location Name: CD #3
API: 05-083-06726



Three 400 bbl. ASTs labeled fresh water.



Flare stack in NE corner of location.

Inspection Photos
Location Name: CD #3
API: 05-083-06726



Shakers on mud pit.



Drilling mud disposal containers.