

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/06/2019

Submitted Date:

03/08/2019

Document Number:

688800477

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
450245 _____ Hughes, Jim _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: _____ 46685 _____
Name of Operator: KINDER MORGAN CO2 CO LP _____
Address: 1001 LOUISIANA ST SUITE 1000 _____
City: _____ HOUSTON _____ State: _____ TX _____ Zip: _____ 77002 _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 11 _____ Number of Comments
1 _____ Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
KinderMorgan		CO2Source_Regulatory@kindermorgan.com	SW Inspection Reports
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
450246	WELL	DG	02/21/2019		083-06726	CD 3	EI

General Comment:

On March 6, 2019 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Kinder Morgan CO2 Co. CD #3. Precision Drilling Rig #829 was on location during this inspection. This environmental field inspection was conducted to investigate Spill/Release Point ID #463123.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Well sign posted near location entrance.		
Corrective Action:			Date:
Type	DRILLING/RECOMP		
Comment:	Signed in from highway.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	ASTs are labeled with contents and capacity.		
Corrective Action:			Date:
Type	OTHER		
Comment:	Hydrogen Sulfide condition status sign near entrance to location. Green flag flying during this inspection.		
Corrective Action:			Date:

Emergency Contact Number:		
Comment:	Posted on location sign	
Corrective Action:		Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:			corrective date
Type: Other	# 1		
Comment:	Precision Drilling Rig #829 and associated equipment on site during this inspection.		
Corrective Action:			Date:

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	3	400 BBLs	STEEL AST		37.544757,-108.893717
Comment:					
Corrective Action:				Date:	

Paint	
Condition	Adequate

Other (Content)	
Other (Capacity)	
Other (Type)	Fresh water

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	8	400 BBLs	STEEL AST		37.545407,-108.893847
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	Labeled fresh water/brine
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Lined secondary containment structure.			
Corrective Action:				Date:

Venting:

Yes/No	
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 450246 Type: WELL API Number: 083-06726 Status: DG Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: DRILLING FLUIDS

Estimated Spill Volume: 40

Comment: [Please refer to Spill/Release Point ID #463123 for more information regarding this release.](#)

Corrective Action: [The operator shall submit a supplemental Spill/Release Report per Rule 906.b. Submit analytical results via a supplement Form 19 upon receipt.](#)

Date: 03/14/2019

Reportable: YES

GPS: Lat 37.545011

Long -108.893749

Proximity to Surface Water:

Depth to Ground Water:

Water Well Complaint:

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Lat

Long

Field Parameters:

Sample Location: _____

Comment: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Drains	Pass					
Waddles	Pass					
Berms	Pass	Gravel	Pass			
Ditches	Pass	Culverts	Pass			
Sediment Traps	Pass					
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On March 6, 2019 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Kinder Morgan CO2 Co. CD #3. Precision Drilling Rig #829 was on location during this inspection. This environmental field inspection was conducted to investigate Spill/Release Point ID #463123.</p> <p>Kinder Morgan representatives Thomas White and Tim Garrett were on site during this inspection. Please refer to Initial Spill/Release Report Document #401960990 for more information regarding this release.</p> <p>Precision Drilling Rig #829 had previously drilled to a TD of 2877' and was tripping back into the hole for a clean out run during this inspection. Company man anticipated running surface casing by 10 PM.</p>	hughesjo	03/08/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800478	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4756901