

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/08/2019

Submitted Date:

03/08/2019

Document Number:

687903874

FIELD INSPECTION FORM

Loc ID 307014 Inspector Name: Stewart, Joseph On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Findings:

- 11 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Roland, Kandis		kroland@hilcorp.com	
Labowskie, Steve		steve.labowskie@state.co.us	
Shorty, Priscilla		pshorty@hilcorp.com	
Ray, Mandi	505-324-5122	mray@hilcorp.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295743	WELL	PR	03/13/2009	GW	067-09551	ALLISON UNIT 116T (LOWER HOL	PR

General Comment:

[Downloadable photos at the end of this inspection report.](#)

Location			
Lease Road:			
Type	Access		
comment:	Gravel Access off county road.		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Framed metal sign attached to fence on produced water tanks.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Emergency contact information up to date. (505) 599-3400		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused Equipment, nuts and bolts and piping around pump jack, unused set of stairs sitting on edge of location.		
Corrective Action:	Please comply with Rule 603.f.		Date: <u>04/08/2019</u>
Type	TRASH		
Comment:	Used compressor plug wires and trash on ground inside compressor building.		
Corrective Action:	Please comply with Rule 603.f.		Date: <u>03/18/2019</u>
Type	TRASH		
Comment:	Soaker pads around pump jack engine and on the ground.		
Corrective Action:	Please comply with Rule 907.e. and Rule 603.f.		Date: <u>03/18/2019</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	TANK BATTERY		
Comment:	T-post and hogwire fencing around produced water tanks.		
Corrective Action:			Date:
Equipment:			
Type: Vertical Heated Separator	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:			

Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:	Compressor is leaking fluid and collecting on compressor skid.		
Corrective Action:	Please comply with Rule 605.d.	Date:	04/08/2019
Type: Pump Jack	# 1		
Comment:	Lube oil leaking from pump jack engine day tank and the gravel below the tank is stained and contaminated. Pump jack engine is leaking oil, localized leak is collecting on pump jack skid and running off skid onto gravel.		
Corrective Action:	Please comply with Rule 605.d. and Rule 907.e.	Date:	04/08/2019
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 295743 Type: WELL API Number: 067-09551 Status: PR Insp. Status: PR**Producing Well**Comment: Producing at time of inspection.

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687903875	Unused Equipment	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4757051
687903876	Oily waste From pump jack engine	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4757052
687903877	Day Tank Leak	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4757053
687903879	Oily Waste	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4757054
687903880	Unused Equipment	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4757055
687903886	Compressor Fluid Leak	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4757056
687903887	Trash	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4757057