

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/01/2019

Submitted Date:

03/02/2019

Document Number:

696100351

FIELD INSPECTION FORM

Loc ID 428960	Inspector Name: Evins, Bret	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: 10110 Name of Operator: GREAT WESTERN OPERATING COMPANY LLC Address: 1001 17TH STREET #2000 City: DENVER State: CO Zip: 80202				Findings: 12 Number of Comments 2 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
,		cogccinspections@gwogco.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
428961	WELL	SI	07/01/2017	OW	123-35597	HCW FD 24-36D	SI
428962	WELL	SI	07/01/2017	OW	123-35598	HCW FD 24-20D	SI
428963	WELL	SI	07/01/2017	OW	123-35599	HCW FD 24-35D	SI

General Comment:

This is a WELL Inspection. (3-wells: SI).
 Battery & ALL equipment is Shut-down.
 Centralized Battery serves 4 Location IDs (416867, 416870, 416873, 428960).
 Refer to FIR #696100349 and/or Location ID #416867 for Battery / Facility, Equipment info.
 2 - Corrective Actions identified.
 1.) HCW FD 24-35D wellsite: NO Emergency contact number posted. See attached photo #2.
 Refer to Rule 210.b for guidance (30 Days). Post Emergency contact number. Comply w/ Rule 210.b
 2.) HCW FD 24-20D, HCW FD 24-36D wellsites: Incorrect well names posted. See attached photo #1, #3.
 COGCC & GPS records indicate the east well on this 3-pad is HCW FD 24-20D, the west well is HCW FD 24-36D.
 Signs that are currently posted for these 2 wells appear to need switched.
 Refer to Rule 210.b for guidance (60 Days). Post correct well signs. Comply w/ Rule 210.b.

Location				
Lease Road:				
Type	Access			
comment:	Adequate			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:) HCW FD 24-20D, HCW FD 24-36D wellsites: Incorrect well names posted. See attached photo #1, #3. COGCC & GPS records indicate the east well on this 3-pad is HCW FD 24-20D, the west well is HCW FD 24-36D. Signs that are currently posted for these 2 wells appear to need switched. Refer to Rule 210.b for guidance (60 Days). Post correct well signs. Comply w/ Rule 210.b			
Corrective Action:	HCW FD 24-20D, HCW FD 24-36D wellsites: Post correct well signs. Comply w/ Rule 210.b			Date: 05/03/2019
Emergency Contact Number:				
Comment:	HCW FD 24-35D wellsite: NO Emergency contact number posted. See attached photo #2. Refer to Rule 210.b for guidance (30 Days). Post Emergency contact number. Comply w/ Rule 210.b			
Corrective Action:	HCW FD 24-35D wellsite: Post Emergency contact number. Comply w/ Rule 210.b			Date: 04/03/2019
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	3-wellsites: Iron panel			
Corrective Action:				Date:
Equipment:				
Type: Plunger Lift	# 3	corrective date		
Comment:				
Corrective Action:				Date:
Type: Other	# 3			
Comment:	3-wellheads: Bradenhead appears plumbed to surface.			
Corrective Action:				Date:
Type:	#			
Comment:	Refer to FIR #696100349 and/or Location ID #416867 for additional Equipment info.			
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY		40.464737,-104.842076	
Comment:	Centralized Battery serves 4 Location IDs (416867, 416870, 416873, 428960). Refer to FIR #696100349 and/or Location ID #416867 for Tanks & Berms info.					
Corrective Action:					Date:	

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 428961 Type: WELL API Number: 123-35597 Status: SI Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: PRODUCTION RECORDSComment: SI. Production valves are closed at well & separator.
COGCC records indicate SI since 07/2017.

Corrective Action: Date:

Facility ID: 428962 Type: WELL API Number: 123-35598 Status: SI Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: PRODUCTION RECORDSComment: SI. Production valves are closed at well & separator.
COGCC records indicate SI since 07/2017.

Corrective Action: Date:

Facility ID: 428963 Type: WELL API Number: 123-35599 Status: SI Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: PRODUCTION RECORDSComment: SI. Production valves are closed at well & separator.
COGCC records indicate SI since 07/2017.

Corrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401958662	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4751663
696100352	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4751659