

Inspection Photos
Operator: Ausco Petroleum Inc.
Location/API #: 043-06216
Date: 2/28/2019



Photo 1. View of the northeastern project area from the access road facing northward. Erosion is occurring in area where arrow is pointing, and long term erosion control is needed in this area.



Photo 2. View of the southern project area from the southeastern corner facing westward. Unused equipment is stored along the outer edges of the well pad.



Photo 3. View of the project area from the southeastern corner facing center. Interim reclamation needs to be conducted as large portions of the well pad do not appear needed for existing production operations. Date of first production was November 22, 2012. Therefore interim reclamation should have been conducted by May 22, 2013.



Photo 4. View of erosional channel approximately 3 feet wide and 2 feet deep, forming in the eastern project area where concentrated stormwater flows off of the well pad.



Photo 5. View of another erosional channel within the eastern project area, approximately 1.5 feet wide and 1 foot deep.



Photo 6. View of unmarked anchor marker in the southeastern project area. Barrels are in lined containment.