

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/05/2019

Submitted Date:

03/05/2019

Document Number:

687903780**FIELD INSPECTION FORM**Loc ID 325355 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10663Name of Operator: ENDURING RESOURCES LLCAddress: 1050 17TH STREET SUITE 2500City: DENVER State: CO Zip: 80265**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
McDaniel, James	505-444-3004	jmcdaniel@enduringresources.com	SW Inspection Reports
Labowskie, Steve		steve.labowskie@state.co.us	
Walter, Kyle		kwalter@enduringresources.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
150332	UIC DISPOSAL	AC	06/01/1993		-	STATE 1-36	AC
214631	WELL	IJ	01/01/2017	DSPW	067-06235	STATE 1-36	IJ

General Comment:[Bradenhead test conducted with Southwest FIU Supervisor Steve Labowskie. Downloadable photos at end of inspection report.](#)

LocationOverall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Old operator name on tank labels. Missing NFPA diamond labels on 400 BBL tanks.		
Corrective Action:	Comply with Rule 210	Date:	04/05/2019

Emergency Contact Number:

Comment:	Correct Contact information.	Date:	
Corrective Action:			

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 150332 Type: UIC API Number: - Status: AC Insp. Status: AC

BradenHead

Comment: There was .3 PSI on bradenhead at start of test with no blowdown when gauge was removed. No changes on tubing and casing during blowdown and no instantaneous pressure.

Corrective Action:

Date:

Facility ID: 214631 Type: WELL API Number: 067-06235 Status: IJ Insp. Status: IJ

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401961407	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4753334
687903781	Missing Tank Labeling	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4753332