

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/05/2019

Submitted Date:

03/05/2019

Document Number:

696100373**FIELD INSPECTION FORM**Loc ID 310388 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292414	WELL	SI	05/01/2017	OW	123-26334	STROMBERGER 13-32	TA

General Comment:

This is a WELL Inspection.

Well is TA.

Battery is Abandoned & ALL equipment except gas meter run has been removed.

Abandoned Battery SE Corner GPS coordinates were: 40.479920,-104.842453

Follow-up to FIR #691200115 dated 05/17/2018.

2 of 2 Corrective Actions from prev. FIR have been addressed.

1.) Access to well was not accessible. Now is accessible.

2.) Unused Equipment at wellsite. Unused Equipment at wellsite now removed. See photos #1-2.

1- Corrective Action identified on this FIR.

1.) Unused meter Run at Abandoned Battery site.

Refer to Rule 603.f for guidance when machinery required to remove equipment (90 Days). See photo #4.

Remove unused gas meter run at Battery site. Comply w/ Rule 603.f.

Location

Lease Road:			
Type	Access		
comment:	Adequate. Access on previous FIR had been unaccessible. Has been addressed.		
Corrective Action	L	Date:	

Overall Good: ☐**Emergency Contact Number:**

Comment:		Date:	
Corrective Action:		Date:	

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused meter Run at Abandoned Battery site. Refer to Rule 603.f for guidance when machinery required to remove equipment (90 Days). See photo #4. Remove unused gas meter run at Battery site. Comply w/ Rule 603.f.		
Corrective Action:	Remove unused gas meter run at Battery site. Comply w/ Rule 603.f.	Date:	06/03/2019
Type	UNUSED EQUIPMENT		
Comment:	Unused Equipment at wellsite from previous FIR has been removed. See photos #1-2.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
In Containment:	No			
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:

Type	WELLHEAD		
Comment:	Iron panel		
Corrective Action:		Date:	

Equipment:

Type: Other	# 1		corrective date
Comment:	Wellhead w/ master & casing head valves.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Bradenhead appears plumbed to surface.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	292414	Type:	WELL	API Number:	123-26334	Status:	SI	Insp. Status:	TA
Idle Well									
Purpose:		<input type="checkbox"/> Shut In		<input checked="" type="checkbox"/> Temporarily Abandoned		Reminder: EQUIPMENT PRESENT/DISCONNECTED			
Comment:		<div>TA. Battery Abandoned. Form 4 #401433843 indicates TA: 04/28/2017. SI/TA well per variance Doc #401474555. (NOBLE).</div>							
Corrective Action:							Date:		

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401961409	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4753335
696100375	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4753333