

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/06/2019

Submitted Date:

03/06/2019

Document Number:

685100627

FIELD INSPECTION FORM

Loc ID 319203 Inspector Name: MEDINA, JUSTIN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Findings:

- 8 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Gomez, Jason		jason.gomez@state.co.us	
, KPK		cogcc@kpk.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
418031	WELL	AL	12/28/2010	LO	123-31817	SRC Pratt 44-29D	AL
418033	WELL	PR	12/01/2017	OW	123-31819	SRC Pratt 34-29D	PR
418034	WELL	PR	12/01/2017	GW	123-31820	SRC Pratt 43-29D	PR
418035	WELL	PR	12/01/2017	GW	123-31821	SRC Pratt 29TD	PR
418036	WELL	PR	12/01/2017	GW	123-31822	SRC Pratt 29XD	PR
421226	WELL	SI	05/01/2018	OW	123-32857	SRC Pratt 29PD	SI
421239	WELL	PR	12/01/2017	OW	123-32862	SRC Pratt 33-29D	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	3 wells on pad have no wellhead name, or #. Well names appear to be on fences scattered around location.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	06/06/2019

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	<input type="text"/>
Corrective Action:	<input type="text"/>		

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	What appears to be 500 BBL tank not being used.		
Corrective Action:	Comply with Rule 603.f .	Date:	06/06/2019
Type	UNUSED EQUIPMENT		
Comment:	What appears to be unused seperator.		
Corrective Action:	Comply with Rule 603.f .	Date:	06/06/2019
Type	DEBRIS		
Comment:	Fencing laying around location, appears to have some of the wellhead signs on them.		
Corrective Action:	Comply with Rule 603.f .	Date:	06/06/2019

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Metal fencing.		
Corrective Action:		Date:	

Equipment:

Type: Horizontal Heated Separator	# 5		corrective date
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID:	418031	Type:	WELL	API Number: 123-31817 Status: AL Insp. Status: AL
Producing Well				
Comment:	One well appears to be SI(SCR Pratt 29PD) others appear to be producing.			Date:
Corrective Action:				Date:
Facility ID:	418033	Type:	WELL	API Number: 123-31819 Status: PR Insp. Status: PR
Facility ID:	418034	Type:	WELL	API Number: 123-31820 Status: PR Insp. Status: PR
Facility ID:	418035	Type:	WELL	API Number: 123-31821 Status: PR Insp. Status: PR
Facility ID:	418036	Type:	WELL	API Number: 123-31822 Status: PR Insp. Status: PR
Facility ID:	421226	Type:	WELL	API Number: 123-32857 Status: SI Insp. Status: SI
Facility ID:	421239	Type:	WELL	API Number: 123-32862 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing wells, one well SI.			Date:
Corrective Action:				Date:

COGCC Comments		
Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On March 6, 2019, at approx 1300, I Justin Medina conducted an on-site inspection at 05-123-32862, KP Kaufman SRC Pratt 33-29D in Weld, Country Colorado.</p> <p>While on location I obserbed producing wells.</p> <p>During the inspection the following possible compliance issues were observed.</p> <p>Missing wellhead signs on 3 wells on location What appears to be unused 500 BBL tank What appears to be unused seperator. What appears to be wellhead fencing, appears that wellhead signs may be on fencing.</p>	medinaj	03/06/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401963311	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4754548
685100628	Location Pictures	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4754525