

Inspection Photos  
Operator: Javernick Oil  
Location/API #: 043-40020  
Date: 2/28/2019



Photo 1. View of the project area from the southern corner facing center.





Photo 2. View of the western project area from the southern corner facing northwestward. Revegetation is progressing within portions of the interim reclamation areas.





Photo 3. View of area in the southeastern project area where stormwater erosion is resulting in erosional scouring and downcutting.





Photo 4. View of debris on the well pad.