

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/07/2019

Submitted Date:

03/07/2019

Document Number:

687903855**FIELD INSPECTION FORM**Loc ID 333076 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Roland, Kandis		kroland@hilcorp.com	
Shorty, Priscilla		pshorty@hilcorp.com	
Ray, Mandy	(505) 599-4083	mray@hilcorp.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
89119	WELL	PR	04/05/2006	GW	067-08223	ALLISON UNIT 19M	PR
292896	WELL	PR	05/20/2008	GW	067-09410	ALLISON UNIT 147T	PR

General Comment:[Downloadable photos at the end of this inspection report.](#)

Location				
Lease Road:				
Type	Access			
comment:	Clay dirt road.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Framed metal sign at wellhead.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Emergency contact information correct. (505) 324-5170			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	UNUSED EQUIPMENT			
Comment:	Unused equipment/parts laying on pump jack, metal signage laying around on the ground by pump jack. Unused batteries on the ground in compressor building. old ball valve laying on ground in compressor building.			
Corrective Action:	Please comply with Rule 603.f.			Date: 04/08/2019
Type	TRASH			
Comment:	Used rags and soaker pads on or around pump jack.			
Corrective Action:	Please comply with Rule 603.f			Date: 04/08/2019
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				
Equipment:				
				corrective date
Type: Pump Jack	# 1			
Comment:				
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 1			
Comment:				
Corrective Action:				Date:
Type: Gas Meter Run	# 2			
Comment:				
Corrective Action:				Date:
Type: Compressor	# 1			
Comment:				

Corrective Action:		Date:	
Type:	#		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 8		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Wellhead		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	PBV STEEL		,
Comment:	Surface water within secondary containment appears to be causing tank to float.				
Corrective Action:	Please comply with Rule 605.e. and 905.b.				Date: 03/10/2019

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
Date:				

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	500 BBLS	STEEL AST		,
Comment:					
Corrective Action:					
Date:					

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
Date:				

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 89119 Type: WELL API Number: 067-08223 Status: PR Insp. Status: PRFacility ID: 292896 Type: WELL API Number: 067-09410 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401964919	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4755732
687903856	Unused Equipment	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4755703
687903857	Trash	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4755704
687903858	Floating Tank 2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4755705
687903859	Unused Equipment	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4755707
687903860	Unused Equipment	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4755709
687903861	Floating Tank 1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4755711
687903864	Signs on ground	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4755713