

Inspection Photos

API: 05-073-06065

Operator: NIGHTHAWK PRODUCTION LLC

Inspection Date: 3/11/2019

Inspection Photos



Photo 1. Facing north along the access road. Vegetation has established along areas of the road.

Inspection Photos




Photo 2. Facing northwest toward the location. Vegetation is establishing in areas of the location.

Inspection Photos



Photo 3. Facing west at the location. This area does not appear to have adequate vegetation cover.

Inspection Photos



Photo 4. Facing east toward the location. Vegetation is establishing in areas of the location.

Inspection Photos



Photo 5. Facing north at the surrounding undisturbed pasture.

Inspection Photos



Photo 6. South of the location at:Lat/Long:38.79662,-103.65101. A chunk of cement remains (red arrow). This appears to be old battery site. A possible cement pad (yellow arrow) can be seen in aerial photo.

Inspection Photos



Photo 7. Yellow arrow points to possible cement pad at the battery site. Follow up inspection needs to be performed to evaluate.