

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/06/2019

Submitted Date:

03/08/2019

Document Number:

688800477

FIELD INSPECTION FORM

Loc ID 450245 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 46685

Name of Operator: KINDER MORGAN CO2 CO LP

Address: 1001 LOUISIANA ST SUITE 1000

City: HOUSTON State: TX Zip: 77002

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

11 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
KinderMorgan		CO2Source_Regulatory@kindermorgan.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
450246	WELL	DG	02/21/2019		083-06726	CD 3	EI

General Comment:

On March 6, 2019 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Kinder Morgan CO2 Co. CD #3. Precision Drilling Rig #829 was on location during this inspection. This environmental field inspection was conducted to investigate Spill/Release Point ID #463123.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	ASTs are labeled with contents and capacity.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Hydrogen Sulfide condition status sign near entrance to location. Green flag flying during this inspection.		
Corrective Action:		Date:	
Type	DRILLING/RECOMP		
Comment:	Signed in from highway.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Well sign posted near location entrance.		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	Posted on location sign
Corrective Action:	
Date:	_____

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Other	# 1		
Comment:	Precision Drilling Rig #829 and associated equipment on site during this inspection.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	3	400 BBLS	STEEL AST		37.544757,-108.893717
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type) Fresh water	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	8	400 BBLs	STEEL AST		37.545407,-108.893847
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	Labeled fresh water/brine
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Lined secondary containment structure.			
Corrective Action:				Date:

Venting:

Yes/No	
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	450246	Type:	WELL	API Number:	083-06726	Status:	DG	Insp. Status:	EI

--

Environmental**Spills/Releases:**Type of Spill: DRILLING FLUIDSEstimated Spill Volume: 40Comment: [Please refer to Spill/Release Point ID #463123 for more information regarding this release.](#)Corrective Action: [The operator shall submit a supplemental Spill/Release Report per Rule 906.b. Submit analytical results via a supplement Form 19 upon receipt.](#)Date: 03/14/2019Reportable: YESGPS: Lat 37.545011Long -108.893749

Proximity to Surface Water:

Depth to Ground Water:

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Drains	Pass					
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	
Sediment Traps	Pass					
Ditches	Pass	Culverts	Pass			
Berms	Pass	Gravel	Pass			
Waddles	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On March 6, 2019 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Kinder Morgan CO2 Co. CD #3. Precision Drilling Rig #829 was on location during this inspection. This environmental field inspection was conducted to investigate Spill/Release Point ID #463123. Kinder Morgan representatives Thomas White and Tim Garrett were on site during this inspection. Please refer to Initial Spill/Release Report Document #401960990 for more information regarding this release. Precision Drilling Rig #829 had previously drilled to a TD of 2877' and was tripping back into the hole for a clean out run during this inspection. Company man anticipated running surface casing by 10 PM.	hughesjo	03/08/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401966231	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4756909
688800478	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4756901