

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/27/2019

Submitted Date:

03/08/2019

Document Number:

693900040**FIELD INSPECTION FORM**Loc ID 322228 Inspector Name: ROY, CATHERINE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 44390Name of Operator: JAVERNICK OILAddress: 3040 E MAINCity: CANON CITY State: CO Zip: 81212**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|-----------------------------------|------------------------|---------------------------------|
| Mehennett, Tom | (719) 275-3040/ (505) 330-1328 | tbm3040@gmail.com | All Inspections |
| Javernick, James | 719-275- 3040/719-671- 3787 | javernick1@gmail.com | All Inspections |
| Javernick, Jim | (719) 275-3040 | javernick1@bresnan.net | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------|
| 210045 | WELL | PR | 06/01/2018 | OW | 043-06124 | CONOCO - SANTA FE 1-6 | RI |

General Comment:[This is an interim reclamation and stormwater inspection.](#)

| Inspected Facilities | | | | | | | | | |
|----------------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 210045 | Type: | WELL | API Number: | 043-06124 | Status: | PR | Insp. Status: | RI |

| |
|--|
| |
|--|

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: Project area is surrounded by pinyon juniper woodland and sagebrush shrubland. Revegetation is progressing within the interim reclamation areas. Tank battery is located south of the project area.**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING _____

Comment Corrective Action

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____Comment Corrective Action

Date _____

1002c. PROTECTION OF SOILS _____

Comment Corrective Action

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment Corrective Action

Date _____

1003a. Waste and Debris removed? PassComment Corrective Action

Date _____

Unused or unneeded equipment onsite? PassComment Corrective Action

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment Corrective Action

Date _____

Guy line anchors marked? _____

Comment Corrective Action

Date _____

| | |
|--------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------|
| Date Final Reclamation Started: _____ | Date Final Reclamation Completed: _____ |
| Final Land Use: _____ | |
| Reminder: _____ | |
| Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div> | |
| Well plugged _____ | Pit mouse/rat holes, cellars backfilled _____ |
| Debris removed _____ | No disturbance /Location never built _____ |
| Access Roads _____ | Regraded _____ Contoured _____ Culverts removed _____ |
| Gravel removed _____ | |
| Location and associated production facilities reclaimed _____ | Locations, facilities, roads, recontoured _____ |
| Compaction alleviation _____ | Dust and erosion control _____ |
| Non cropland: Revegetated 80% _____ | Cropland: perennial forage _____ |
| Weeds present _____ | Subsidence _____ |
| 1004.d. FINAL VEGETATION TRANSECT | |
| TRANSECT RESULTS OF DISTURBED AREA% _____ | |
| TRANSECT RESULTS OF REFERENCE AREA% _____ | |
| TOTAL % OF DESIRABLE VEGETATION COVER _____ | |
| VEGETATIVE COVER _____ | |
| Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div> | |
| Corrective Action: <div style="border: 1px solid black; height: 20px; width: 100%;"></div> | |
| Overall Final Reclamation _____ | Well Release on Active Location <input type="checkbox"/> Multi-Well Location <input type="checkbox"/> |

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: Erosion is occurring where concentrated stormwater runs off of the eastern well pad.

Corrective Action: Stormwater controls need to be installed to stabilize erosion within the eastern project area.

Date: 04/12/2019

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 401966518 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4757297 |
| 693900041 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4757289 |