

**Inspection Photos**  
**Location Name: BOUNCER 41-27 AND TR**  
**API #: 05-071-07610**  
**Insp. Doc. # 695100349**



**PHOTO 1: LOCATION**



**PHOTO 2: WELL SIGN/METER HOUSE**



## Inspection Photos

Location Name: BOUNCER 41-27 AND TR

API #: 05-071-07610

Insp. Doc. # 695100349



**PHOTO 3: TR WELLHEAD**



**PHOTO 3: PRODUCED WATER IN PIT IS ABOVE THE 2' FREEBOARD.**



**Inspection Photos**  
**Location Name: BOUNCER 41-27 AND TR**  
**API #: 05-071-07610**  
**Insp. Doc. # 695100349**



**PHOTO 5: PRODUCED WATER IN PIT IS ABOVE THE 2' FREEBOARD.**



**PHOTO 6: PRODUCED WATER IN PIT IS ABOVE THE 2' FREEBOARD.**



## Inspection Photos

Location Name: BOUNCER 41-27 AND TR

API #: 05-071-07610

Insp. Doc. # 695100349



**PHOTO 7: FREEBOARD MARKER IS IMPROPERLY INSTALLED  
ON THE HIGHER ELIVATION SIDE OF PIT.**

