

Inspection Photos
Location Name: TYRANNOSAURUS 43-22
API #: 05-071-07533
Insp. Doc. # 695100351



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN/METER HOUSE

Inspection Photos

Location Name: TYRANNOSAURUS 43-22

API #: 05-071-07533

Insp. Doc. # 695100351



PHOTO 3: IMPACTED SOIL ON EAST SIDE OF ENGINE SKID



PHOTO 4: IMPACTED SOIL ON EAST SIDE OF SKID AT END OF EXHAUST PIPE OUTLET.