

Inspection Photos
Location Name: APPALOOSA 42-22
API #: 05-071-07547
Insp. Doc. # 695100353



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN/METER HOUSE

Inspection Photos
Location Name: APPALOOSA 42-22
API #: 05-071-07547
Insp. Doc. # 695100353



PHOTO 3: OIL FROM ENGINE IS RUNNING DOWN CONCRETE BLOCK AND IMPACTING SOIL.



PHOTO 4: IMPACTED SOIL NEAR EXHAUST PIPE ON EAST SIDE OF ENGINE SKID.

Inspection Photos
Location Name: APPALOOSA 42-22
API #: 05-071-07547
Insp. Doc. # 695100353



**PHOTO 5: PRODUCED WATER IS ABOVE 2' FREEBOARD. I
COULD NOT FIND A FREEBOARD MARKER**



**PHOTO 6: ANOTHER VIEW OF PRODUCED WATER LEVEL
ABOVE 2' FREEBOARD.**