

Inspection Photos
Location Name: SANTA FE 43-27 AND TR
API #: 05-071-07803
Insp. Doc. # 695100355



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN/METER HOUSE

Inspection Photos

Location Name: SANTA FE 43-27 AND TR

API #: 05-071-07803

Insp. Doc. # 695100355



PHOTO 3: IMPACTED SOIL ON EAST SIDE OF COMPRESSOR



PHOTO 4: IMPACTED SOIL IN SEVERAL SPOTS ON SOUTH SIDE OF ENGINE SKID

Inspection Photos

Location Name: SANTA FE 43-27 AND TR

API #: 05-071-07803

Insp. Doc. # 695100355



PHOTO 5: IMPACTED SOIL BETWEEN ENGINE SKID AND WELLHEAD ALONG HYDRAULIC HOSES



PHOTO 6: IMPACTED SOIL IN SEVERAL SPOTS AROUND WELLHEAD



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: SANTA FE 43-27 AND TR

API #: 05-071-07803

Insp. Doc. # 695100355



PHOTO 7: IMPACTED SOIL ON WEST SIDE OF COMPRESSOR

Inspection Photos
Location Name: SANTA FE 43-27 AND TR
API #: 05-071-07803
Insp. Doc. # 695100355

Calibration

Report Date **1/30/18 12:48 PM**

Section 1 - Meter

Device ID **100107803**

Location **SANTA FE 43-27**

Section 2 - Setup

Current Plate Size	0.75	Tap Type	Pipe
Pipe Size	2.067	SP Tap Location	Up Stream
Atmos. Pressure	11.3	Temperature Bias	0
Pressure Base	14.73	Temperature Base	60

Plate Inspected? ☒ Yes ☐ No

Edges Sharp? ☒ Yes ☐ No

Plate Mic'd? ☒ Yes ☐ No

Seal Ring Damaged? ☒ Yes ☐ No

Colorado Oil & Gas Conservation Commission
 37.141, -104.86814, 2170.0m, 286°
 2019/03/15 14:37:47

Calibration Report

Report Date **1/30/18 1:14 PM**

Section 1 - Meter

Device ID **100108303**

Location **SANTA FE 43-27 TR**

Section 2 - Setup

Current Plate Size	0.625	Tap Type	Pipe
Pipe Size	2.067	SP Tap Location	Up Stream
Atmos. Pressure	11.4	Temperature Bias	-3
Pressure Base	14.73	Temperature Base	60

Plate Inspected? ☒ Yes ☐ No

Edges Sharp? ☒ Yes ☐ No

Seal Ring Damaged? ☒ Yes ☐ No

Plate Mic'd? ☒ Yes ☐ No

Pitted? ☒ Yes ☐ No

Tube Inspected? ☒ Yes ☐ No

Dirty? ☒ Yes ☐ No

Colorado Oil & Gas Conservation Commission
 37.14099, -104.86814, 2170.0m, 336°
 2019/03/15 14:37:32

PHOTO 8: CALIBRATION LOG IS PAST DUE ON BOTH WELLS

PHOTO 9: CALIBRATION LOG IS PAST DUE ON BOTH WELLS