

Inspection Photos
Location Name: PACHECO 33-27 TR
API #: 05-071-08384
Insp. Doc. # 695100357



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN/METER HOUSE

Inspection Photos
Location Name: PACHECO 33-27 TR
API #: 05-071-08384
Insp. Doc. # 695100357



PHOTO 3: IMPACTED SOIL ON NORTH SIDE OF METER HOUSE



PHOTO 4: IMPACTED SOIL ON WEST SIDE OF ENGINE SKID

Inspection Photos

Location Name: PACHECO 33-27 TR

API #: 05-071-08384

Insp. Doc. # 695100357



PHOTO 5: IMPACTED SOIL ON EAST SIDE OF ENGINE SKID



PHOTO 6: IMPACTED SOIL ON EAST SIDE OF COMPRESSOR



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: PACHECO 33-27 TR
API #: 05-071-08384
Insp. Doc. # 695100357

Calibration

Report Date **1/30/18 1:34 PM**

Section 1 - Meter

Device ID **100108384**

Location **PACHECO 23-27 TR**

Section 2 - Setup

Current Plate Size	0.875	Colorado Oil & Gas Conservation Commission
Pipe Size	2.067	37-14162, -104.87454, 2146.0m, 255°
Atmos. Pressure	11.4	2019/03/15 15:08:14

PHOTO 7: CALIBRATION IS PAST DUE