



**Location**

Overall Good:

**Signs/Marker:**

Type	OTHER				
Comment:	WELL SIGN ON METER HOUSE				
Corrective Action:					Date:

**Emergency Contact Number:**

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER				
Comment:	APPEARS SEPARATOR IS BEING DRAINED ON LOCATION CAUSING IMPACTED SOIL. SEE LOCATION PHOTOS FOR DETAILS.				
Corrective Action:	Comply with Rule 603.f .				Date: <u>04/15/2019</u>

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

					corrective date
Type: Other	# 1				
Comment:	BREADENHEAD IS PLUMBED TO SURFACE				
Corrective Action:					Date:
Type: Gas Meter Run	# 1				
Comment:	ACCORDING TO CALIBRATION REPORT IN METER HOUSE THE CALIBRATION IS PAST DUE.				
Corrective Action:	MEASURE GAS ACCORDING TO RULE 329				Date: <u>04/15/2019</u>
Type: Ancillary equipment	# 1				
Comment:	TELEMETRY EQUIPMENT				
Corrective Action:					Date:

**Venting:**

Yes/No	NO				
Comment:					
Corrective Action:					Date:

**Flaring:**

Type					
Comment:					
Corrective Action:					Date:

**Inspected Facilities**

Facility ID: 266000 Type: WELL API Number: 071-07809 Status: PR Insp. Status: PR

**Producing Well**

Comment:		
Corrective Action:		Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695100361	LOCATION PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4765067">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4765067</a>