

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/11/2019

Submitted Date:

03/11/2019

Document Number:

694400103

FIELD INSPECTION FORM
 Loc ID 318529 Inspector Name: Kraich, Adam On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 16910

Name of Operator: CHURCHILL ENERGY INC

Address: 8177 SOUTH NORFOLK STREET

City: ENGLEWOOD State: CO Zip: 80112

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Kraich, Adam	970-420-0536	Adam.Kraich@state.co.us	(Area 117) Field Operations
Carroll, Kathy	(303) 987-0241	kc2121@prodigy.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241510	WELL	PR	04/01/2018	GW	123-09299	STROMBERGER UNIT 2-12	PR

General Comment:

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Signage at battery has incorrect or non working contact numbers. See Photo# 4Corrective Action: Install sign to comply with 210.bDate: 02/11/2019Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Other

1

Comment: Wellhead master valve appears to be broken. See Photo #3Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.Date: 01/11/2019**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	400 BBLS	STEEL AST		,

Comment: Crude oil tank load out valve has developed a leak. See photo #2Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.Date: 01/11/2019**Paint**

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:

Corrective Action:

Date:

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 241510 Type: WELL API Number: 123-09299 Status: PR Insp. Status: PR**Producing Well**

Comment: On Monday March 11th I, Adam Kraich, Performed an inspection of the Stromberger 2-12 well and location. Location ID 318529. Well API# 123-09299.
 This is a follow up inspection to document #674301438
 At time of inspection, I observed the following conditions:
 Leaking load line valve on production tank. See Photo #1. Citing 605.d
 Appears to be a broken master valve on wellhead. See photo #2. Citing 605.d
 Signage emergency contact information is not accurate. See photo #3, Citing 210.b
 No corrections have been made in regard to the aforementioned issues.
 END.

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401968618	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4759529
694400104	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4759509