

# Inspection Photos

3/18/2019

Operator: VERDAD RESOURCES LLC # 10651

Location ID: 462872

Inspection Doc. Number: 682504597

Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: VERDAD RESOURCES LLC # 10651  
Location ID: 462872



**Photo 1:** Photo taken from the southeast corner of the location, facing west. Photo provides overview of construction in-process. Photo also shows operator failed to install perimeter stormwater and erosion control BMPs prior to construction activities in accordance with Rule 1002.f and COAs from the permitted 2A

Inspection Photos  
Operator: VERDAD RESOURCES LLC # 10651  
Location ID: 462872



**Photo 2:** Photo taken from the southeast corner of the location, facing north. See comments under photo 1.

Inspection Photos  
Operator: VERDAD RESOURCES LLC # 10651  
Location ID: 462872



**Photo 3:** Photo taken from the northeast end of the location, facing west. Photo shows topsoil stockpile. Ensure BMPs are implemented to protect stockpiled soils in accordance with 1002.c



**Photo 4:** Photo taken from the northeast corner of the location, facing south. See comments under photo 1.

Inspection Photos  
Operator: VERDAD RESOURCES LLC # 10651  
Location ID: 462872



**Photo 5:** Photo taken from the northeast corner of the location, facing west. See comments under photo 1.



**Photo 6:** Photo taken from the topsoil stockpile on the north end of the location, facing west. See comments under photo 1.



**Photo 7:** Photo taken from the northwest corner of the location, facing east. See comments under photo 1.



**Photo 8:** Photo taken from the northwest corner of the location, facing south. See comments under photo 1.

Inspection Photos  
Operator: VERDAD RESOURCES LLC # 10651  
Location ID: 462872



**Photo 9:** Photo taken from the southwest corner of the location, facing north. See comments under photo 1.

Inspection Photos  
Operator: VERDAD RESOURCES LLC # 10651  
Location ID: 462872



**Photo 10:** Photo taken from the southwest corner of the location, facing east. See comments under photo 1.