

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/12/2019

Submitted Date:

03/12/2019

Document Number:

688401488**FIELD INSPECTION FORM**Loc ID 428424 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 19035Name of Operator: OVERLAND RESOURCES LLCAddress: SUITE C18 PMB 440City: GREENWOOD State: CO Zip: 80121**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments5 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Anderson, Robert	303-800-6175	admin@overlandresourcesllc.com	
Gillette, Kira		kira.gillette@state.co.us	
Pandolfo, Chris	630-387-6506	admin@overlandresourcesllc.com	All Inspections
Gomez, Jason		jason.gomez@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
428427	WELL	SI	07/01/2017	OW	001-09744	Handke 3	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign not posted or information inaccurate at well(s) or battery		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	11/12/2018
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Load lines to crude oil and H2O production tanks do not have bullplugs		
Corrective Action:	Location is within a designated setback location, bullplug or cap all loadlines per Rule 604.c.(2)O.	Date:	03/18/2019
Type	OTHER		
Comment:	Stained soil around crude oil load out line spill container and lines inbetween crude oil tanks.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with Rule 907.e.. Contact area COGCC EPS	Date:	11/12/2018
Type	OTHER		
Comment:	Mechanical issues with piping to load out line to spill container and tank leveling lines inbetween tanks		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	03/13/2019
Type	WEEDS		
Comment:	Weeds around TNK BTRY and Separators		
Corrective Action:	Comply with rule 603 f	Date:	11/02/2018

Overall Good: ☐

Spills:			
Type	Area	Volume	
In Containment: No			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type			

Inspected Facilities									
Facility ID:	428427	Type:	WELL	API Number:	001-09744	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: <input type="text" value="SI"/>									
Corrective Action: <input type="text"/> Date: _____									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday March 12 2019 at approximately 1135hrs, I Randy Silver, conducted a follow up on-site inspection at an Overland Resources location Handke #3 API# 05-001-09744 in Adams Colorado.</p> <p>While there, I observed a Production facility.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>No sign on WH Rule 210 b CAD of 11-12-2018 see photos 1.</p> <p>Stained soil Rule 603 f CAD of 11-12-18 see photos 3,4,5,6,7,8.</p> <p>Load lines not bull plugged Rule 604 c (2) O CAD of 3-18-19 see photos 9 and 10.</p> <p>Mechanical issues Rule 605 d CAD of 3-13-19 see photos 3,4,5,6,7,8.</p> <p>Weeds Rule 603 f CAD of 11-2-18 see photos 11 and 12</p> <p>This was a follow up inspection per DOC# 688400418 all corrective actions had not been addressed at time of inspection.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	silverr	03/12/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401970775	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4761592
688401489	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4761569