



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |  |
|------|------|--------|--|--|--|
|      |      |        |  |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type WELLHEAD

Comment: [Fencing around pump jack & electrical equip.](#)

Corrective Action:

Date:

**Equipment:**

corrective date

Type: Other

#

Comment: [Bradenhead plumbed to surface.](#)

Corrective Action:

Date:

Type: Pump Jack

# 1

Comment: [Unused pump jack on location. Refer to Document # 691400185 previous inspection was reported also.](#)

Corrective Action: [Comply with Rule 603.f .](#)

Date: 07/12/2018

Type: Plunger Lift

# 1

Comment:

Corrective Action:

Date:

Type: Prime Mover

# 1

Comment:

Corrective Action:

Date:

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 242669 Type: WELL API Number: 123-10460 Status: PR Insp. Status: PR

**Producing Well**

Comment: What appears to be leaking gasket between tubing head, and casing head. See pic 4

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 07/12/2018

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

| Comment   | User    | Date       |
|---|---------|------------|
| <p><b>COGCC Inspection Report Summary</b><br/>                     On March 19, 2019 at approximately 1200 I, Inspector Justin Medina, conducted an on-site inspection at KP Kaufman 123-10460 in Weld County Colorado.<br/>                     While there, I observed producing well.<br/>                     Unused pump jack on location. Refer to Document # 691400185 previous inspection was reported also. Comply with 603.f Delinquent since 7/12/2018</p> <p>What appears to be a leak off of the A and B section of well. See pic 4<br/>                     Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.<br/>                     This is a summary of inspection report.</p> | medinaj | 03/19/2019 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description   | URL   |
|--------------|---------------|---|
| 685100666    | Location Pics | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4767706">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4767706</a> |