

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/12/2019

Submitted Date:

03/13/2019

Document Number:

682600646**FIELD INSPECTION FORM**
 Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
 _____ Kosola, Jason _____ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 96340Name of Operator: WIEPKING-FULLERTON ENERGY LLCAddress: 96 GLENMOOR LNCity: ENGLEWOOD State: CO Zip: 80113**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------------|----------------|-------------------------------|---------------------------------|
| Shalberg, Greg | 719-688-3547 | gregshalberg@aol.com | all inspections |
| Boone, Linda | (720) 271-8605 | LDBoonePar@aol.com | All Inspections |
| Herian, Tim | (316) 655-9200 | therian1@cox.net | All Inspections |
| Halde, Kerry | 719-346-0653 | haldeoil@hotmail.com | |
| Schlagenhauf, Mark | | mark.schlagenhauf@state.co.us | |

General Comment:

The Aloha Mula 16 off location flowline experienced a pipeline failure on or about 1 pm on Sunday, March 10th, approximately halfway between the wellhead and the tank battery. Spill location is 39.162861, -103.598569. Spill flowed south on surface. Operator has repaired leak and is in the process of removing contaminated soil.

Operator shall submit a Form 27 Remediation to area Environmental Protection Specialist by April 1st, 2019.

Inspection found no impact to surface water.

Environmental**Spills/Releases:**

Type of Spill: OIL

Estimated Spill Volume: 20

Comment: Operator reported spill of crude oil from pipeline rupture. Spill volume estimated by inspector.

Corrective Action: By April 1, 2019, submit a Form 27 Site Investigation and Remediation Workplan with a proposed workplan and timeline for remediation of this release.

Date: 04/01/2019

Reportable: YES

GPS: Lat 39.162861

Long -103.598569

Proximity to Surface Water: 9200

Depth to Ground Water:

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 401971177 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4761934 |
| 682600647 | COGCC Spill Map | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4761928 |
| 682600648 | Inspection photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4761930 |