

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/15/2019

Submitted Date:

03/15/2019

Document Number:

695100351

FIELD INSPECTION FORM

Loc ID 308109 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10084
Name of Operator: PIONEER NATURAL RESOURCES USA INC
Address: 5205 N O'CONNOR BLVD STE 200
City: IRVING State: TX Zip: 75039

Findings:

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|-------------------------|--------------|----------------------------|---------------------------------|
| Distribution, Evergreen | | cogcc.evergreen@enrllc.com | All Inspections |
| Distribution, Pioneer | 972-444-9001 | COGCC.Inspections@pxd.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 261956 | WELL | PR | 02/04/2003 | GW | 071-07533 | TYRANNOSAURUS 43-22 | PR |

General Comment:

(This area is intentionally left blank for general comments.)

| Location | | | |
|--|---|--------|-------------------------|
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | OTHER | | |
| Comment: | WELL SIGN ON METER HOUSE | | |
| Corrective Action: | | Date: | |
| Emergency Contact Number: | | | |
| Comment: | | | |
| Corrective Action: | | | Date: _____ |
| Good Housekeeping: | | | |
| Type | OTHER | | |
| Comment: | IMPACTED SOIL APPEARS TO BE STAINED WITH OIL ON EAST SIDE OF ENGINE SKID. IMPACTED SOIL APPEARS TO BE STAINED FROM EXHAUST FROM ENGINE ON EAST SIDE OF ENGINE SKID | | |
| Corrective Action: | Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. | | Date: <u>04/15/2019</u> |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Equipment: | | | |
| Type: Ancillary equipment | # 1 | | corrective date |
| Comment: | TELEMETRY EQUIPMENT | | |
| Corrective Action: | | Date: | |
| Type: Other | # 1 | | |
| Comment: | BREADENHEAD IS PLUMBED TO SURFACE | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | LAST CAL. 4/10/19. METER WILL NEED CALIBRATED WITHIN THE NEXT 26 DAYS. | | |
| Corrective Action: | | Date: | |
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected FacilitiesFacility ID: 261956 Type: WELL API Number: 071-07533 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 401974890 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4765073 |
| 695100352 | LOCATION PHOTOS | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4765063 |