

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/15/2019

Submitted Date:

03/15/2019

Document Number:

695100355

**FIELD INSPECTION FORM**

Loc ID 333716 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10084

Name of Operator: PIONEER NATURAL RESOURCES USA INC

Address: 5205 N O'CONNOR BLVD STE 200

City: IRVING State: TX Zip: 75039

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Pioneer	972-444-9001	COGCC.Inspections@pxd.com	<a href="#">All Inspections</a>
Distribution, Evergreen		cogcc.evergreen@enrllc.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
266005	WELL	PR	06/16/2003	GW	071-07803	SANTA FE 43-27	PR
276208	WELL	PR	04/15/2005	GW	071-08303	SANTA FE 43-27 TR	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	BOTH WELL SIGNS ON METER HOUSE		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:	Date: _____		

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	IMPACTED SOIL IN SEVERAL SPOTS AROUND WELLHEAD, ENGINE SKID AND COMPRESSOR. SEE LOCATION PHOTOS FOR DETAILS.		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A.		Date: 04/15/2019

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Other	# 2		
Comment:	BREADENHEADS ON BOTH WELLS ARE PLUMBED TO SURFACE		
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:	WELL APPEARS TO BE PRODUCED ON A VACUUM WITH NO FORM 4 SUNDRY NOTICE ON FILE		
Corrective Action:	SUBMIT DOCUMENTATION THAT THE WELL IS NOT BEING PRODUCED ON A VACUUM OR SUBMIT FORM 4 SUNDRY NOTICE FOR APPROVAL TO PRODUCE WELL ON VACUUM IN ACCORDANCE WITH RULE 331		Date: 04/15/2019
Type: Ancillary equipment	# 2		
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	CALIBRATION REPORT IS PAST DUE ON BOTH WELLS		
Corrective Action:	Measure gas per Rule 329.		Date: 04/15/2019

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

**Inspected Facilities**Facility ID: 266005 Type: WELL API Number: 071-07803 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Facility ID: 276208 Type: WELL API Number: 071-08303 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401974892	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4765075">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4765075</a>
695100356	LOCATION PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4765065">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4765065</a>