

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/18/2019

Submitted Date:

03/18/2019

Document Number:

687904018**FIELD INSPECTION FORM**
 Loc ID 326087 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:15 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Inspections, All		SanJuanCOGCC@bp.com	All Inspections
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215841	WELL	PR	05/31/1990	GW	067-07446	KG TRUST 1	PR

General Comment:[Location is still covered in snow during time of inspection. Downloadable photo at the end of this inspection report.](#)

Location				
Lease Road:				
Type	Access			
comment:	Gravel road with locked gate at entrance off the county road.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Framed metal sign at entrance to location.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Emergency contact information current. (970) 247-6916			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	TRASH			
Comment:	Some trash on the ground inside the sound walls.			
Corrective Action:	Please comply with Rule 603.f.			Date: 03/28/2019
Type	UNUSED EQUIPMENT			
Comment:	Unused piping and valve cluster sitting along sound wall.			
Corrective Action:	Please comply with Rule 603.f.			Date: 04/18/2019
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Cattle panels around pumpjack and wellhead.			
Corrective Action:				Date:
Type	SEPARATOR			
Comment:	Cattle panels around separator and meter house.			
Corrective Action:				Date:
Equipment:				
Type: Bird Protectors	# 1			corrective date
Comment:	On separator stack.			
Corrective Action:				Date:
Type: Gas Meter Run	# 1			
Comment:				

Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead with access to bradenhead.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 12		
Comment:	Sound wall around wellhead, pump jack and compressor.		
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:	Might want to take a look at your compressor on site. Engine was loud and the exhaust may be coming loose from the manifold off the engine.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 215841 Type: WELL API Number: 067-07446 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401976485	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4765996
687904019	Unused equipment and trash	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4765995