

Inspection Photos
Operator: Hilcorp Energy
Location/API #: 067-09929
Date: 2-18-2019



Photo 1. View of the project area from the project entrance facing center. Erosion is occurring at the entrance and water is ponded on the well pad.



Photo 2. View of erosional rilling occurring within the northern project area, facing eastward.



Photo 3. View of the eastern fill slope from the northeastern edge facing southward.



Photo 4. View of the western project area from the southwestern corner facing northward. Interim reclamation has not been conducted.



Photo 5. View of the southern project area from the southwestern edge facing eastward.