

PIT STATUS EVALUATION FORM

Facility ID: 115162

Pit Name: KEEN 24-1

☐ Duplicate Record(s) Pit #



Legend

- ☒ Database Pit Location
- ☐ Producing Well
- ☐ Shut In Well
- ☐ Temp Aban Well
- ☐ Abandoned Well
- ☐ Dry & Aban Well
- ☐ Injection Well
- ☐ Other Well Status



1:6,000
0 250 500 750 Feet

Image Source:
USDA National Agricultural Imagery
Program (NAIP), 2006

 S.S. PAPADOPOULOS & ASSOCIATES, INC.

COGCC Database Information

Status: NR Owner: ORM EXPLORATION CO
T: 6S R: 62W Sec: 1 QQ: SESEW 6th Meridian
Latitude: 39.551237 Longitude: -104.284539 NAD83

County: Elbert, CO
County Code: 039

Pit Status Evaluation

- ☐ Active ☐ Form 15: Pit Permit N/A Assoc. Well Seq No(s) _____
☐ Other documentation _____
☐ Aerial photo verification _____
- ☒ Closed ☐ Form 27: Remediation Workplan _____
☐ Form 4: Sundry Notice _____
☐ Rule 903a.(2)B _____
☒ Evidence pit(s) existed, no closure docs & well not PR, AC or SI
Well API Seq #(s) 06464 PA (7-15-1987)
☒ Other documentation FIR# 440663 (5-13-98) . FIR# 500141510 (3-4-99)
WSIF# (12-4-89)
- ☐ Abandoned ☐ Possible un-reclaimed pit(s) or adverse conditions, no closure docs ☐ Site Visit
☐ No Site Visit
☐ Add'l Review
- ☐ Unknown

Notes: LIF (1987) Fiberglass skim tank
FIR (1998) "well plugged & location restored". Gas meter flowline riser still at site."
WSIF (1989) Pits backfilled & site clean