

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/20/2019

Submitted Date:

03/20/2019

Document Number:

687904134**FIELD INSPECTION FORM**Loc ID 333870 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**19 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Inspections, All		SanJuanCOGCC@bp.com	All Inspections
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264750	WELL	IJ	04/01/2018	DSPW	067-08758	BARNES WTR DISP WELL (EPA) 1	IJ
269138	WELL	PR	08/20/2003	GW	067-08860	JOHN BARNES A 2	PR

General Comment:[Facility inspection of above ground equipment. Downloadable photo at end of inspection report.](#)

Location					
Lease Road:					
Type	Access				
comment:	Well maintained gravel road with multiple gates through private property.				
Corrective Action	L				Date:
Overall Good: <input type="checkbox"/>					
Signs/Marker:					
Type	TANK LABELS/PLACARDS				
Comment:	Tank labels with NFPA, contents and volume clearly marked on all tanks.				
Corrective Action:					Date:
Type	OTHER				
Comment:	Safety signs posted at doors to all buildings.				
Corrective Action:					Date:
Type	WELLHEAD				
Comment:	Framed metal signs at entrance to location.				
Corrective Action:					Date:
Emergency Contact Number:					
Comment:	Emergency contact information posted on framed metal signs at entrance as well as on doors to entrances of buildings. (970) 247-6916/911				
Corrective Action:					Date:
Overall Good: <input checked="" type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Fencing/:					
Type	SEPARATOR				
Comment:	Cattle panels around separator.				
Corrective Action:					Date:
Type	WELLHEAD				
Comment:	Cattle panels around wellheads.				
Corrective Action:					Date:
Type	LOCATION				
Comment:	Barbed wire fence around entire facility.				
Corrective Action:					Date:
Equipment:					
Type: Other	#			corrective date	
Comment:	Injection well building, Injection pump building, valve control building, Motor control center building (MCC)				
Corrective Action:					Date:

Type: Ancillary equipment	# 2	
Comment:	Wellheads.	
Corrective Action:		Date:
Type: Bird Protectors	# 3	
Comment:	2 on 750 BBL tanks, 1 on Separator.	
Corrective Action:		Date:
Type: Deadman # & Marked	# 5	
Comment:	Carsonite markers on ground at deadmen from plowing snow.	
Corrective Action:		Date:
Type: Gas Meter Run	# 2	
Comment:		
Corrective Action:		Date:
Type: Vertical Heated Separator	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	PBV STEEL		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	STEEL AST		,
Comment:	Produced water tanks are 750 BBL each. Thief hatch on T-1427-1 is open.				
Corrective Action:	comply with Rule 605.d.				Date: 03/27/2019

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Inspector Name: Stewart, Joseph

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Concrete	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	264750	Type:	WELL	API Number:	067-08758	Status:	IJ	Insp. Status:	IJ
Producing Well									
Comment:	Producing.								
Corrective Action:						Date:			
Facility ID:	269138	Type:	WELL	API Number:	067-08860	Status:	PR	Insp. Status:	PR

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					Berm around location Perimeter.
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			
				Material Handling And Spill Prevention	Pass	

Comment: 10 BBL fiberglass tank with sufficient secondary containment outside of injection well building.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401979936	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4769100
687904135	Thief hatch.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4769094