

# Inspection Photos

Operator: Rim Operating  
Location/API #: 067-08933  
Date: 2-18-2019



Photo 1. View of project area from the southeastern corner facing center.





Photo 2. View of the southern project area from the southeastern edge facing westward. Revegetation is comprised of dense rubber rabbitbrush (*Chrysothamnus nauseosus*).





Photo 3. View of metal and wood debris within the project area.





Photo 4. View of erosional channel approximately 1.5 feet wide and deep within the eastern project area.





Photo 5. View of an erosional channel approximately 1.5 feet wide and deep within the southern project area.