

Inspection Photos

Location Name: ZUESS FEDERAL 11-10

API #: 05-071-09529

Insp. Doc. # 695100399



PHOTO 1: LOCATION

**PHOTO 2: WELL SIGN IS BROKE OFF MOUNTING POINT
LAYING OF LOCATION NEAR METER RUN**

Inspection Photos

Location Name: ZUESS FEDERAL 11-10

API #: 05-071-09529

Insp. Doc. # 695100399



PHOTO 3: PACKING IS SPRAYING PRODUCED WATER OUT ON LOCATION.



PHOTO 4: IMPACTED SOIL ON NORTH SIDE NEAR ENGINE SKID



Inspection Photos

Location Name: ZUESS FEDERAL 11-10

API #: 05-071-09529

Insp. Doc. # 695100399



PHOTO 5: IMPACTED SOIL NEAR BACK (SOUTHEAST) SIDE OF ENGINE SKID



PHOTO 6: NORTHEAST ANCHOR MARKER IS DOWN

