

Inspection Photos
Location Name: Thomas Jacquez E #1
API: 05-067-07590



Broken jug of oil additive dripping into secondary containment.



Area of stained gravel and wet area beneath valve.

Inspection Photos
Location Name: Thomas Jacquez E #1
API: 05-067-07590




Stained soil at truck load out valve.



Paint on tank is peeling off.

Inspection Photos
Location Name: Thomas Jacquez E #1
API: 05-067-07590



Sign for 21 bbl. was laying face down upon arrival.



Area beneath valve is wet and surrounding area is stained.

Inspection Photos
Location Name: Thomas Jacquez E #1
API: 05-067-07590



Overflowing 5 gallon bucket.



Oil underneath compressor.