

Inspection Photos

Location Name: COLUMBINE SPRINGS FEDERAL 3-14-4-104

Location ID: 05-103-08566

Inspection: 679703543




Photo 1. Location looking northeast.



Photo 2. Blow down tank.

Gas leaks



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: COLUMBINE SPRINGS FEDERAL 3-14-4-104

Location ID: 05-103-08566

Inspection: 679703543




Photo 3. Well head on infrared with a FLIR GF320 camera.




Photo 4. Well head in infrared HSM with a FLIR GF320 camera.

Inspection Photos

Location Name: COLUMBINE SPRINGS FEDERAL 3-14-4-104

Location ID: 05-103-08566

Inspection: 679703543




Photo 5. Well head on infrared with a FLIR GF320 camera.

Gas leak




Photo 6. Well head in infrared HSM with a FLIR GF320 camera.

Inspection Photos

Location Name: COLUMBINE SPRINGS FEDERAL 3-14-4-104

Location ID: 05-103-08566

Inspection: 679703543




Photo 7. Tubing valve on infrared with a FLIR GF320 camera.

Gas leak




Photo 8. Tubing valve in infrared HSM with a FLIR GF320 camera.

Inspection Photos

Location Name: COLUMBINE SPRINGS FEDERAL 3-14-4-104

Location ID: 05-103-08566

Inspection: 679703543




Photo 9. Casing valve end in infrared HSM with a FLIR GF320 camera.

Gas leak



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources