

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/26/2019

Submitted Date:

04/03/2019

Document Number:

689802440**FIELD INSPECTION FORM**Loc ID 447512 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10598Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLCAddress: 123 ROBERT S KERR AVECity: OKLAHOMA CITY State: OK Zip: 73102**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Neidel, Kris		kris.neidel@state.co.us	
Ash, Margaret		margaret.ash@state.co.us	
Inspections, General		sandridgeenvironmental@san dridgeenergy.com	<a href="#">All Inspections</a>
Fischer, Alex		alex.fischer@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
447586	WELL	DG	09/02/2018		057-06581	Peters 0781 15-13H12	SI
447587	WELL	DG	09/04/2018		057-06582	Peters 0781 13-13H12	SI
447589	WELL	DG	09/07/2018		057-06583	Peters 0781 11-13H12	SI
447590	WELL	DG	09/08/2018		057-06584	Peters 0781 9-13H12	SI

**General Comment:**

[Routine FIU follow-up inspection. Follow up to inspection from 2/25/2019 document number 689802357. No corrective actions have been met.](#)

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Debris present all over location, including but not limited to: pile of oily hoses and secondary containment at entrance, square secondary containment vessels with oily fluid in them and hoses coming out, turned over stock tank that appears to have been used for secondary containment, turned over chemical tote, hoses with no containment.		
Corrective Action:	Comply with Rule 603.f .	Date:	04/12/2019
Type	OTHER		
Comment:	Drips, stained soil, non-reportable spills observed all over location.		
Corrective Action:	Comply with Rule 603.f .	Date:	04/12/2019
Type	STORAGE OF SUPL		
Comment:	Frack tanks stored on location with incomplete secondary containment.		
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 906.d.(1).	Date:	04/12/2019

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment: Inspector observed tank being installed as part of construction activities. It did not appear a liner had been installed beneath the tank.					
Corrective Action: Comply with Rule 605.a(4) or provide evidence of compliance via FIRR.					Date: 04/12/2019

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
<b><u>Venting:</u></b>					
Yes/No					
Comment:					
Corrective Action:					Date:
<b><u>Flaring:</u></b>					
Type					
Comment:					
Corrective Action:					Date:

**Inspected Facilities**Facility ID: 447586 Type: WELL API Number: 057-06581 Status: DG Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Corrective Action:  Date: \_\_\_\_\_Facility ID: 447587 Type: WELL API Number: 057-06582 Status: DG Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Corrective Action:  Date: \_\_\_\_\_Facility ID: 447589 Type: WELL API Number: 057-06583 Status: DG Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Corrective Action:  Date: \_\_\_\_\_Facility ID: 447590 Type: WELL API Number: 057-06584 Status: DG Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Corrective Action:  Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No stormwater BMPs apparent. Large amounts of mud and snowmelt on location.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689802441	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4783036">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4783036</a>