

Inspection Photos

API: 05-071-07413

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 4/2/2019

Inspection Photos



Photo 1. There is signs of erosion and vehicle rutting along the road that travels up to the location.

Inspection Photos



Photo 2. There is some oil on the engine skid.

Inspection Photos



Photo 3. Facing toward the location. Vegetation is well established in the interim reclamation area.