

Maralex Resources Inc. .

Api # 05-077-08622

Inspection # 675002120



Photo of location From NW corner of the location

Maralex Resources Inc. .
Api # 05-077-08622
Inspection # 675002120



**Photo #2. Unused poly pipe along side of upper access road
East of location**



**Photo # 3. Unused poly pipe along side of upper access road.
Poly line runs along access road east of location going south
toward location 077-09438 location for a different Operator**

Maralex Resources Inc. .
Api # 05-077-08622
Inspection # 675002120



Photo #4. Unused poly pipe along side of upper access road East of location



Photo #5 Looking West onto location from upper access road. Unused poly pipe along North side of location

Maralex Resources Inc. .

Api # 05-077-08622

Inspection # 675002120



Photo #6 . Unused poly pipe along North side of location, up the hill headed East off location



Photo #7. Unused poly pipe along North side of location with unmarked riser.

Maralex Resources Inc. .

Api # 05-077-08622

Inspection # 675002120



Photo #8. Storm Water Erosion moving sediment off location from NW access entrance. Sediment moving onto main access road.



Photo #9. Erosion is evident along unsterilized slope on the north side of location .

Maralex Resources Inc. .

Api # 05-077-08622

Inspection # 675002120



Photo #10. Storm Water Erosion moving sediment across location from east hillside onto access road below



Photo #11. Storm Water Erosion moving heavy sediment across location from east hillside onto access road below

Maralex Resources Inc. .
Api # 05-077-08622
Inspection # 675002120



Photo #12. Storm Water Erosion moving sediment off the SW entrance of location onto main access road.



Photo #13. Storm water leaving location, crossing main access road and moving down valley into ravine. BMP not maintained.

Maralex Resources Inc. .
Api # 05-077-08622
Inspection # 675002120



Photo #14. Storm Water Erosion moving sediment of hillside, across location and onto access road



Photo #15. (close up of photo 14) Storm Water Erosion moving sediment of hillside, across location and onto access road