

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/04/2019

Submitted Date:

04/04/2019

Document Number:

679600584

FIELD INSPECTION FORM

Loc ID 333063 Inspector Name: Santistevan, Brittani On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

14 Number of Comments

4 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kraich, Adam		adam.kraich@state.co.us	
,		NBL_DJBU_Inspections@NB LENERGY.COM	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292971	WELL	PR	12/03/2018	GW	123-26429	NOFFSINGER F 2-4	PR
292972	WELL	SI	11/01/2018	OW	123-26428	NOFFSINGER F 2-5	PR

General Comment:

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate (x2)		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused tubing (north of gas meter house/seperator) See attached photo.		
Corrective Action:	Comply with Rule 603.f .	Date:	05/04/2019
Type	UNUSED EQUIPMENT		
Comment:	Unused pipe (east side of tank battery) See attached photo.		
Corrective Action:	Comply with Rule 603.f .	Date:	05/04/2019
Type	OTHER		
Comment:	Appears to be stained soil under master valve. See attached photo.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	05/04/2019
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment in gas meter house. See attached photo.		
Corrective Action:	Comply with Rule 603.f .	Date:	05/04/2019

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel (x2)		
Corrective Action:		Date:	

Type	TANK BATTERY		
Comment:	Wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.435000,-104.636600
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	BV CONCRETE		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
-----------	----------	--

Other (Content)	
Other (Capacity) 60 BBLS	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Shares containmet with crude oil tank.				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 292971 Type: WELL API Number: 123-26429 Status: PR Insp. Status: PR

Producing Well

Comment: <u>PR</u>	
Corrective Action:	Date:

Facility ID: 292972 Type: WELL API Number: 123-26428 Status: SI Insp. Status: PR

Producing Well

Comment: <u>PR</u>	
Corrective Action:	Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday, April 4, 2019 at approximately 11:57, I, Inspector Brittani Santistevan, conducted an on-site inspection at Noffsinger F 2-4, 5 (Noble Energy), at location #: 333063 in Weld County, Colorado. While there, I observed producing wells. During this inspection the following possible compliance issues were observed: 1. Unused tubing (north of gas meter house/separator). Comply with Rule 603.f . (Corrective Action Date: May 4, 2019) See attached photo #6. 2. Unused pipe (east side of tank battery). Comply with Rule 603.f . (Corrective Action Date: May 4, 2019) See attached photo #5. 3. Appears to be stained soil under master valve. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. (Corrective Action Date: May 4, 2019) See attached photo #2. 4. Unused equipment in gas meter house. Comply with Rule 603.f . (Corrective Action Date: May 4, 2019) See attached photo #4.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p> <p>Continuiing education inspection.</p>	santistb	04/04/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679600585	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4784447
679600586	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4784448