


PIT STATUS EVALUATION FORM

Facility ID: 111797
 Pit Name: DUFFY 10-3

Duplicate Record(s) Pit #

111796



Legend

- Producing or Shut In Well
- Temp Aban Well
- Abandoned Well
- Dry & Aban Well
- Earthen Pit
- Culvert
- Backfilled Pit(s)
- Vault
- Fiberglass Tank
- Steel Tank(s)
- Separator
- Wellhead
- Earthen Pit Extent
- Area of Disturbance
- Backfilled Pit Extent
- Tank Fence



Image Source:
 USDA National Agricultural Imagery Program (NAIP), 2006

S.S. PAPADOPULOS & ASSOCIATES, INC.

COGCC Database Information

Status: NR Owner: K P KAUFFMAN COMPANY INC
 T: 7S R: 63W Sec: 10 QQ: NENW 6th Meridian
 Latitude: 39.462085 Longitude: -104.433949 NAD83

County: Elbert, CO
 County Code: 039

Pit Status Evaluation

- Active** Form 15: Pit Permit #846306 (1998) existing Assoc. Well Seq No(s) TA (2005) 06459PA(12-6-01)
 Other documentation FORM 21 #1496117 (4-20-2005), NOVA #119754 (10-22-2004)
 Aerial photo verification
- Closed** Form 27: Remediation Workplan _____
 Form 4: Sundry Notice _____
 Rule 903a.(2)B _____
 Evidence pit(s) existed, no closure docs & well not PR, AC or SI
 Well API Seq #(s) _____
 Other documentation _____
- Abandoned** Possible un-reclaimed pit(s) or adverse conditions, no closure docs Site Visit
 No Site Visit
 Add'l Review
- Unknown**

Notes: No lease inspections for Facility ID#111797. NOVA #119754 (2004) indicates well maintain TA status until 4-20-2010.
Field Visit 6-4-2008: Earthen Pit & Culvert found. Heavily oil saturated soils & pit cover / berm unsatisfactory.



Photo 1. Well site - temporarily abandoned well status



Photo 2. Earthen pit and culvert



Photo 3. Culvert and cover



Photo 4. Wellhead equipment