

**Inspection Photos**  
**Location Name: UPRR 43 Pan AMB#11**  
**Location ID: 318578**



**Photo 1 WH piping from injection line to WH has been removed no gauge on tubing on top of WH**



**Photo 2 Unused equipment: unknown tank, misc parts and roll of wire**

**Inspection Photos**  
**Location Name: UPRR 43 Pan AMB#11**  
**Location ID: 318578**



**Photo 3 no gauge on top of WH**



**Photo 4 casing 1150psig**



**Inspection Photos**  
**Location Name: UPRR 43 Pan AMB#11**  
**Location ID: 318578**



**Photo 5 Braden head 0 psig**