

Inspection Photos
Location Name: Evans 0780 21
Location ID: 438250



Photo 1. No liner apparent under tank install. Non-reportable spills, stained soil in foreground and background.



Photo 2. Example of cuttings on location perimeter berm.

Inspection Photos
Location Name: Evans 0780 21
Location ID: 438250



Photo 3. Example of cuttings on location perimeter berm.



Photo 4. Example of cuttings on location.

Inspection Photos
Location Name: Evans 0780 21
Location ID: 438250



Photo 5. Example of cuttings on location perimeter berm, debris and trash also present on berm.



Photo 6. Non-reportable spill, stained soil.

Inspection Photos
Location Name: Evans 0780 21
Location ID: 438250



**Photo 7. Non-reportable spill at hammer union.
Free product and stained soil.**



Photo 8. Close-up of photo 5.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 689802462

Inspection Photos
Location Name: Evans 0780 21
Location ID: 438250



Photo 9. Non-reportable spill at hammer union. Stained soil.



Photo 10. Non-reportable spill at hammer union. Free product and stained soil.

Inspection Photos
Location Name: Evans 0780 21
Location ID: 438250



Photo 11. Non-reportable spil. Stained soil.



Photo 12. Non-reportable spill. Free product and stained soil.

Inspection Photos
Location Name: Evans 0780 21
Location ID: 438250



Photo 13. Non-reportable spil. Stained soil.



Photo 14. Non-reportable spill. Stained soil.